

# Transformadores Monofásicos

TMP / Ps

## Dimensionais Mecânicos

Potência (VA)	A [máx] (mm)	B [ $\pm 2$ ] (mm)	C [máx] (mm)	D [ $\pm 1$ ] (mm)	E [máx] (mm)	F [ $\pm 1$ ] (mm)	Massa (kg)
50	77	63.5	65	40	95	OBL 5x10	1,2
70	77	63.5	70	45	95	OBL 5x10	1,4
100	77	63.5	77	52	95	OBL 5x10	1,9
150	86	70	85	60	105	OBL 5x13	2,2
200	98	80	91	66	114	OBL 5x13	2,8
250	98	80	102	77	114	OBL 5x13	3,4
300	98	80	106	81	114	OBL 5x13	3,7
350	122	100	112	83	136	OBL 7x12	5
500	152	125	110	77	165	OBL 7x12	6,6
650	152	125	125	92	165	OBL 7x12	8,3
750	152	125	135	102	165	OBL 7x12	9,5
1010	182	150	125	94	193	OBL 10x18	10
1300	182	150	135	104	193	OBL 10x18	12
1500	182	150	150	119	193	OBL 10x18	14,7
2000	242	200	135	96	245	OBL 10x18	15,2
2500	242	200	155	116	245	OBL 10x18	20,5
3000	242	200	155	116	245	OBL 10x18	21,3

